

# OT2 Recovery Checklist

22

- Bung out and in cuddy bag.
- Engine tilt locked
- Tie down front + safety line
- Store all recovery items dolphin bag.
- Prop cover on
- Kill cord away tool box
- Spray hood away
- Roller furling down
- Sail tie furling Genoa make neat sheet and control line.
- Lazy jacks to shrouds tie off.
- Halyards to cleats
- Mast down.
- Burgee off and stow
- Strap mast bag with halyards in
- Strap rest of mast.
- Mast prop in. Secure to cleats
- Mast and furling on rest. Lash down. Strap to each other
- Rudder in bag.
- Tiller on top
- Weight down spray hood
- Tie on light board.
- Ratchet strap.